

## BULLETIN TECHNIQUE 2014 n°4


### 208 R2

28 mars 2014

#### Colonne de direction

Le fourreau de colonne de direction, référence 1E4520176D, comporte un système d'absorption de chocs.

Nous vous rappelons qu'il est indispensable de contrôler régulièrement l'état de la colonne de direction, notamment suite à des chocs importants au niveau du train avant, et plus particulièrement des pièces d'absorption et de guidage représentées ci-dessous :



Il est indispensable de remplacer la colonne de direction si l'une de ces pièces est endommagée.

## TECHNICAL BULLETIN 2014 n°4


### 208 R2

28<sup>th</sup> March 2014

#### Steering column

The steering column, reference 1E4520176D, includes a shock absorption system.

We remind you it is essential to control regularly the column and its absorption system to be sure it is not damaged, especially after important shocks with the front axle:



It is indispensable to replace the steering column if one of these parts is damaged.

## **CONTACTS**

### **Peugeot Sport**

3, rue Marcel Dassault

BP 68

78143 VELIZY Cedex

[www.peugeot-sport.com](http://www.peugeot-sport.com)

### **Équipe d'assistance technique 208 R2**

#### **Technical Support Team for 208 R2**

Jean-François GRANDCLAUDON

Responsable Assistance Technique

Technical Support Manager

Tél. : + 33 (0)1 30 70 22 74

Email : [jeanfrancois.grandclaudon@mpsa.com](mailto:jeanfrancois.grandclaudon@mpsa.com)

Jean-Charles FLATTIN

Tel : + 33 (0)1 30 70 21 43

E-mail : [jeancharles.flattin@mpsa.com](mailto:jeancharles.flattin@mpsa.com)

### **Racing Shop - Vente de pièces / Parts dealer**

Tél. : + 33 (0)1 61 45 95 55

Fax : + 33 (0)1 30 70 21 03

Email: [peugeotsport-racingshop@peugeot.com](mailto:peugeotsport-racingshop@peugeot.com)

Website : [www.peugeotsport-store.com](http://www.peugeotsport-store.com)