

## BULLETIN TECHNIQUE 2016 n°04


### 208R2

13 juin 2016

#### Raccord étrier frein avant (réf. [216708-21](#)) :

Afin d'optimiser l'étanchéité du montage du [circuit de freinage de votre 208R2](#), le **raccord d'étrier de frein avant de référence [216708-21](#)** doit être utilisé avec le **joint cuivre associé référence [PS81535A10](#)**.

Il est également conseillé de contrôler la propreté de l'ensemble ainsi que le bon centrage du joint cuivre une fois l'assemblage réalisé.



## TECHNICAL BULLETIN 2016 n°04


### 208 R2

June, 13<sup>th</sup> 2016

#### Front brake caliper coupling (PN [216708-21](#)) :

In order to optimize the assembly of [the brake circuit of your 208R2](#), the brake caliper coupling PN [216708-21](#) has to be fitted, together with the corresponding copper seal PN [PS81535A10](#).

We also advise you to check the cleanliness of the assembly and the proper centering of the copper seal once the coupling tightened on the caliper.



## CONTACTS

### BOUTIQUE PEUGEOT CITROEN RACING SHOP

2 Rue Gay Lussac

95500 Gonesse

Tel : +33 (0) 1 30 11 27 00

E-mail : [racingshop@mpsa.com](mailto:racingshop@mpsa.com)

Web : [www.peugeot-sport-store.com](http://www.peugeot-sport-store.com)

### CONSEILLERS TECHNIQUES

Thomas BELUCHE

Tel : + 33 (0)1 30 84 06 83

E-mail : [thomas.beluche@mpsa.com](mailto:thomas.beluche@mpsa.com)

Josselyn GAL

Tel : + 33 (0)1 30 70 22 74

Mob : + 33 (0)6 72 82 07 94

E-mail : [josselyn.gal@mpsa.com](mailto:josselyn.gal@mpsa.com)

Yann CHALMETON

Tel : + 33 (0)1 30 84 03 06

Mob : + 33 (0)6 31 83 00 89

E-mail : [yann.chalmeton@mpsa.com](mailto:yann.chalmeton@mpsa.com)

### Responsible Assistance Technique

Christophe VELY

Tel : + 33 (0)1 30 84 03 98

Mob : + 33 (0)7 61 51 37 92

E-mail : [christophe.vely@mpsa.com](mailto:christophe.vely@mpsa.com)